CERTIFICATE OF STRUCTURAL STABILITY

Date: 27 /10/2021

Name of Structure: Vidya Prasarak Mandal School
Address: Mithaghar Road, Mulund East, Jaihind Colony, LIC Housing Colony, Mulund East, Mumbai, Maharashtra 400081
Age: 56 Years (As per client)

This is to certify that the structure Vidya Prasarak Mandal School, Mulund (E) is been visited and inspected by me fully externally as well as internally. The structure was repaired recently. On the basis of visual inspection and results of Non-destructive tests performed the structure was found to be good in condition and could continue to perform the same as present for its intended use for 5 years provided the structure needs to be monitored under my observation every year.

The following parameters are permanently excluded from capacity of this certificate

1. Damages and deteriorations observed after my inspection / date of certificate.
2. Codal compliances of existing structural design as structural drawings were not available.
3. Soil stability and relevant information was not available.
4. This report and its recommendations will remain preliminary as it is based upon visual inspection of structural members and non-Destructive tests performed.
5. The structural stability/performance of existing design doesn't comprise (loads due to seismic / wind / natural calamities/ activities or accidents or fire outbreak) due to non-availability of structural drawings.
6. Change in the mode of use from commercial (school) to industrial or any other modes. etc.
7. Any damages to adjoining College structures which impose a loading to school building.

27/10/2021

NIKHIL MHATRE
STR/M/840000996

Nikhil N. Mhatre
M.Tech Structures (VJTI)
Chartered Engineer
MCGM STR/M/840000996

e-cube Concrete Consultants LLP
THANE
Tel.: 022-21720444